

1
FIG.




FIG. 2




FIG. 3






FIG. 4



4/6


FIG. 5



A: TEMPERATURE IN CHAMBER IS 7°C OR MORE
EVAPORATION TEMPERATURE: 0°C
ROTATION NUMBER: 50~60Hz
TEMPERATURE IN CHAMBER DROPS FROM 7°C
EVAPORATION TEMPERATURE: -10°C
ROTATION NUMBER: 30~50Hz

B: TEMPERATURE IN CHAMBER
EVAPORATION TEMPERATURE: -10°C
ROTATION NUMBER: 30~50Hz

FIG. 6



6/6

FIG. 7

